

HD160-E

Heavy Duty Ride-on Industrial Sweeper

PRESTART & OPERATION CHECKLIST



STEP 1
Read your Daily Operations Manual



STEP 2
Ensure clean path is free of strapping & large debris



STEP 3
Visually check over machine




STEP 4
Turn key to ON position and depress accelerator



STEP 5
Move throttle to maximum RPM




STEP 6
Ensure hopper is completely down & secure



STEP 7
Activate main broom



STEP 8
Open hopper door




STEP 9
Start fan. Fan MUST be running while sweeping



STEP 10
Depress accelerator pedal to move and control speed


DAILY MAINTENANCE




STEP 1
Raise main broom to home position



STEP 2
Close hopper door flap




STEP 3
Activate filter shaker for 30 seconds



STEP 4
Raise hopper to maximum height



STEP 5
Position hopper over waste receptacle




STEP 6
Open hopper door




STEP 7
Reverse by depressing bottom of foot pedal



STEP 8
Ensure broom is free from strapping



STEP 9
Lower waste hopper



STEP 10
Complete battery maintenance weekly



STEP 11
Plug in to charge for minimum of 8 hours



STEP 12
Report any damage

COMMON CONSUMABLES

PART NUMBER	DESCRIPTION
3007760	Main Broom
3007959	Side Broom