

HDA-K900 Daily Checklists

(Guide only for autonomous floor cleaning robots)

1. Operator has read and understood operator and maintenance manual.
2. Ensure operator is sufficiently train on all functions of the robot sweeper machine.
3. Check area the robot sweeper is to be used in is in accord with "Permissible conditions of use" (Free from strapping, shrink wrap, large slopes and other dangers)
4. **Visually check over sweeper:**
 - Docked & charged and hopper has been emptied.
 - Rubber dust skirts.
 - Vacuum dust filter is clean.
 - Wheels & traction.
 - Functions & controls.
5. Use machine in accord with operator and maintenance manual via online system
6. Empty debris hopper after every use.
7. Shake filter clean after every use.
8. Ensure machine docks & charges correctly.

All inquiries: 1800 100 150

Parts inquiries: parts@conquesteg.com

Service Inquiries: service@conquesteg.com